
# Revolution TONNO (NOTE: Springs are at cab end.) Tarp Assembly with Cab Rail, Tail Rail and Support Bows attached. MISSING PARTS??? call Extang at

Clamps (x 2)

Wrench



PARTS INCLUDED IN YOUR KIT. You may want to lay them out in this manner for accessibility.

Left and Right Side Rail Assemblies


Extang Corporation 5400 S. State Rd. Ann Arbor MI 48108 734-677-0444, Fax: 734-677-8409


(x6)


Register your warranty at: **extang.com** 


1-800-877-2588
Any and all needed parts will be shipped to you directly.


(DO NOT return whole kit to store)














## **Parts List**

See Part Descriptions on Back



Extang Corporation 5400 S. State Rd. Ann Arbor MI 48108 734-677-0444, Fax: 734-677-8409 extang.com

Item No. 0176-1603 RH Printed in U.S.A.



## Parts List

NOTE: To order replacement parts, it's best to contact our Customer Service Department for assistance, to ensure getting the correct part for your vehicle application. When ordering, xxx represents the 3 digit suffix, as referenced on the sales receipt or vehicle application list. Additional parts information can be found on our website, at http://extang.com/how.html. Customer Service: 800-877-2588

53xxx\* Black Replacement Tarp 54xxx-55\* Side Rail Replacement Assembly (1) 1087\* Bow End Assembly (1) 32540297 Siderail Tarp Seal 8' 27540100 Bow End Extender (1) 1076 Siderail Seal 8' 27540300 Extender Spring (1) 1082 Side Rail End Plugs (2) 1083 Bow Clip Assembly 35541400 Right Side Tapered Bow Plug (1) 25004400 1/4"- 20 x 1/4" SHCS (1) 35541500 Left Side Tapered Bow Plug (1) 26003300 Weld Nut (1) 54xxx-10\* Cab Bow w/End Caps (1) 35540600 Bow Clip (1) 54xxx-11\* Ctr Bow w/End Caps (1) 1090 Passenger-side Rear Latch Assembly (1) 54xxx-12\* Cab Ctr Bow (L/B only) w/End Caps (1) 25004300 1/4"- 20 x 5/8" SHCS (1) 54xxx-13\* Tail Ctr Bow (L/B only) w/End Caps (1) 26003200 Weld Nut (1) 54xxx-14\* Tail Bow w/End Caps (1) 35540900 Pivot Block (1) 27480100 Latch Spring (1) 54xxx-26\* Clamp Pack (set of 2) 21540301 Adjusting U-clamp w/hole (1) 26007700 Clevis Hitch Pin (1) 25000400 1/4"-20 x 1" SHCS (1) 26007900 Clevis Latch Pin (1) 25005200 1/4"-20 x 2.5" Hex (1) 27540600 Latch (1) 25005400 1/4"-20 x 4" Hex (1) 1091 Driver-side Rear Latch Assembly (1) 26001000 1/4"Plastic Acorn Nut (1) 25004300 1/4"- 20 x 5/8" SHCS (1) 26001100 1/4"Jam Nut (4) 26003200 Weld Nut (1) 54xxx-35\* Cabrail Replacement Assembly 26007700 Clevis Hitch Pin (1) 32540366 Cab/Tail Rail Seal (1) 26007900 Clevis Latch Pin (1) 32540363 68" Black Foam Roll 27480100 Latch Spring (1) 27540700 Latch (1) 1078 Cabrail Tarp Strap Assembly S/B (1) 35540900 Pivot Block (1) 1088 Cabrail Tarp Strap Assembly L/B (1) 1092 Passenger-side Front Latch Assembly (1) 25003500 1/4"-20x1/2" SHCS (1) 25004300 1/4"- 20 x 5/8" SHCS (1) 26003200 Weld Nut (1) 25005400 1/4"- 20 x 4" Hex Head (1) 26005000 1/4" Washer (1) 26000300 1/4" Nut (1) 54500100 Strap for S/B (1) 26003200 Weld Nut (1) 54540100 Strap for L/B (1) 26007700 Clevis Hitch Pin (1) 1085R Right Side Cab/Tail Plunger Assembly 26007900 Clevis Latch Pin (1) 1085L Left Side Cab/Tail Plunger Assembly 27480100 Latch Spring (1) 27540200 Cab/Tail Rail Extender (1) 27540800 Tension Spring (1) 27540300 Extender Spring (1) 27540700 Latch (1) 35540100 End Cap Clip (1) 35480100 Stanchion (1) 35540400 Right Side Lrg Cab/Tail End Plug (1) 35540900 Pivot Block (1) 35540500 Left Side Lrg Cab/Tail End Plug (1) 1093 Driver-side Front Pivot Assembly (1) 35541000 Right Side Sm Cab/Tail End Plug (1) 25004300 1/4"- 20 x 5/8" SHCS (1) 35541100 Left Side Sm Cab/Tail End Plug (1) 25005400 1/4"- 20 x 4" Hex Head (1) 1077 Slide Lock Assembly 26000300 1/4" Nut (1) 25003700 Thumbscrew (1) 26003200 Weld Nut (1) 26003200 Weld Nut (1) 27540800 Tension Spring (1) 35480500 Slide Lock (1) 35480100 Stanchion (1) 54xxx-45 Tail Rail Replacement Assembly 35540900 Pivot Block (1) 32540163 Tail Rail Seal (1) 1085R Right Side Cab/Tail Plunger Assembly Miscellaneous 1085L Left Side Cab/Tail Plunger Assembly 28001000 3/16" Hex Key (1) 27540200 Cab/Tail Rail Extender (1) 27540300 Extender Spring (1) 35540100 End Cap Clip (1) 35540400 Right Side Lrg Cab/Tail End Plug (1) \* Specify: Year, Make, Model, **35540500** Left Side Lrg Cab/Tail End Plug (1) Long-bed or Short-bed, Driver or 35541000 Right Side Sm Cab/Tail End Plug (1)



Extang Corporation 5400 S. State Rd. Ann Arbor MI 48108 734-677-0444, Fax: 734-677-8409

35541100 Left Side Sm Cab/Tail End Plug (1)

Register your warranty at: **extang.com** 

Passenger side.



### READ CAREFULLY - KEEP IN A SAFE PLACE

PLEASE ATTACH AND SAVE YOUR SALES RECEIPT.
ACTIVATE YOUR WARRANTY ONLINE AT EXTANG.COM.

**Maximum Strength Warranty** - <u>Lifetime</u> <u>frame</u> <u>and</u> <u>tarp</u> warranty covers the following tonneaus: Revolution, Express, Trifecta and eMAX.

### **WARRANTY DURATION:**

**Lifetime Frame** – Extang offers a LIFETIME warranty against defective materials or workmanship on the Revolution, Express, Trifecta and eMAX rails, aluminum components, clamps, bows, hardware. **Lifetime Tarp** – Extang offers a LIFETIME warranty against defective materials or workmanship on the Revolution, Express, Trifecta and eMAX vinyl covering.

### **WARRANTY CONDITIONS:**

This warranty is against defective materials or workmanship. The warranty is void if the product has been damaged by accident, unreasonable use, neglect, improper service/installation/removal, modifications, normal wear and tear or other causes not arising out of defective materials or workmanship. Consequential and incidental damages are not covered under this warranty.

### THE FOLLOWING CONDITIONS WILL ALSO VOID THE WARRANTY:

- Wind whip damage Tarps must be secured at all points when vehicle is in motion. An unsecured tarp will flap, resulting in damage to the fabric.
- Improper cleaning It is recommended to use the tested and approved Extang Tonno Tonic<sup>™</sup> or clean with soap and water only. Do not use vinyl conditioners (i.e. Armor All®) because they will shrink the vinyl.
- Overloading of cargo Cargo should not touch the tonneau's tarp at any point. Protrusions in the tarp will stress the fabric. Cargo may shift while traveling and cause it to push against the tarp fabric and damage it.

The warranty applies to the original consumer/purchaser. Warranty registration must be on file and/or proof of original purchase (detailed and dated receipt) required for warranty to be effective. Warranty coverage starts from the date of purchase.

### PERFORMANCE:

Provided all warranty conditions are met Extang will either repair or replace (at Extang's option) the product or component. Extang may require the original item to be returned postage prepaid for final determination. Extang reserves the right to substitute and offer the respective warranty discount on an entire replacement system or provide other remedies than those listed in this warranty for discontinued products or other reasons. A return authorization number must be obtained from our customer service department prior to returning any product. Shipping charges will apply for any repair or replacement. This warranty gives you specific legal rights and you may also have other legal rights which vary from state to state.

## 2-MAX









### TRIFFCTA



### HELPFUL ACCESSORIES





The MaxSeal Tailgate Seal creates a tight seal along sides and bottom of your tailgate to keep out dust, rain and snow. Quick and easy to install: just cut, peel and stick.





B-Light, Tonneau Lighting System works well with soft and hard tonneau covers. Contains 8 high-intensity LED units. Simple and easy to install and comes with a 1 year warranty.

Order today, direct from our customer service department:

1-800-877-2588

5400 S. STATE ROAD, ANN ARBOR, MI 48108 VOICE: **734-677-0444** or **800-877-2588** FAX: 734-677-8409 EMAIL: info@extang.com

WEB SITE: extang.com



No. 0030-11.13RRE Printed in U.S.A.

# DID YOU KNOW?

EXTANG TONNEAUS MAY IMPROVE GAS MILEAGE UP TO 10%

### HERE'S HOW:

There are conservatively 850,000 Extang Tonneaus on the road everyday and based on the average gas savings, Extang tonneaus save America 102 million gallons of gas per year or approximately \$382,500,000.

Studies show the average truck owner drives 18,000 miles per year. At 15 mpg that comes to 1,200 gallons of gas. At a minimum 10% savings <u>you</u> would save around 120 gallons of gas a year. You can see why it would not take too many months to have your new tonneau pay for itself.



"...adding a tonneau could mean an improvement in fuel mileage that is the equivalent of a free gallon of gas for every 20 gallons used."

- Auto Trim & Restyling News, August 2001


MILES DRIVEN PER YEAR	MPG	AVERAGE GAS COST	ANNUAL GAS SAVINGS	ANNUAL COST SAVINGS	3 YEARS COST SAVINGS	5 YEARS COST SAVINGS	MONTHS FOR TONNO PAY BACK
12,000	15	\$3.75	80 gal.	\$300	\$900	\$1,500	12
15,000	15	\$3.75	100 gal.	\$375	\$1,125	\$1,875	9
18,000	15	\$3.75	120 gal.	\$450	\$1,350	\$2,250	8
20,000	15	\$3.75	133 gal.	\$498	\$1,494	\$2,490	7
22,000	15	\$3.75	146gal.	\$547	\$1,641	\$2,735	6

Results are based on an estimated tonneau price of \$300.00 and rounded to the nearest whole number. Savings may vary and are not guaranteed.



# SOMETHING DAMAGED? MISSING PARTS?

WE CAN HELP YOU QUICKLY AND EASILY OVER THE PHONE




Experienced Customer Service staff to answer all your tonneau questions


CUSTOMER SERVICE HOURS: 8:30 TO 5 EST, MONDAY - FRIDAY

Tonno Model:
Purchase Date:
Lot Code:
Lot code can be found on underside of cover.



HARDWARE KIT INCLUDES 2 SPECIALLY DESIGNED ADJUSTABLE CLAMPS.





- Rear clamps are adjustable to keep tail end of side rail square to bed. Use shortest bolt that engages sidewall.
- See Step 4 of installation instructions for clamp placement.

